



GROSSMONT-CUYAMACA
COMMUNITY COLLEGE DISTRICT

Cuyamaca College: Automotive Technology Series
CA BAR-Approved Emission Training Program

Fall 2011 SCHEDULE

Smog Check Program - 2011 Update Training Course (16 hour)

The Bureau of Automotive Repair (BAR) requires all licensed Smog Check technicians whose LICENSE EXPIRES AFTER JANUARY 1, 2011 to complete the "2011 Update Training Course" prior to renewing their license.

You will receive your course materials the first night of class!

These courses meet for 4 evenings - 4 hours each night. The course will cover the following subject areas:

- Smog Inspection Procedures
- New BAR Technician Performance Evaluation Program (STARS)
- Aftermarket Parts & CAT Labeling
- OBD II Practical Processes, including: circuit testing, sensors, outputs & actuators, General Diag. Strategies, Readiness Monitors, Mode \$06
- CAT Testing: cranking test, snap throttle test, Invasive test, light-off test, misfire test, temperature test, 4 gas test
- OBD II Monitor testing

To pass the course, students will be required to:

- Complete all home work assignments
- Successfully complete all laboratory assignments
- Attend all scheduled course hours
- Pass final exam

***Dates:**

November 2,7,9,14	Mon/Wed 6-10 pm	Room K-114	SECTION # 9108
December 6,8,13,15	Tues/Thurs 6-10 pm	Room K-104	SECTION # 9109

Location: Cuyamaca College, Automotive Technology Complex

To Register:

Go to www.cuyamaca.edu/preview click on WebAdvisor – Click Here to Register. Next click on the yellow bar titled Continuing Ed. Next, under the Registration heading, click on “register and pay for Continuing Education classes”. Next type the word smog in the “search for” section.

Fee: \$295

The good news: Successful completion of this 16 hour course (including completing all required lab assignments and passing the written final exam) continues to take the place of the previously required state smog exam (only for those who are renewing a current license). As soon as you finish this course, send your renewal application to the BAR and you are done (assuming your ASE or alternative certificates are not expired).

You must bring a picture ID and Smog License # (if you have a license) to class.

**If you need assistance registering on-line, please call
Continuing Education (619) 660-4350**